

ASBESTOS BUILDING INSPECTION REPORT

for

Michigan State University
Office of Environmental Safety
East Lansing, Michigan 48824-1101

at

Michigan State University
Old Horticulture Building #25
East Lansing, Michigan 48824

Investigation conducted by

Fibertec Industrial Hygiene Services, Inc.
1914 Holloway Drive
Holt, Michigan 48842

Project #24990-1

Project Duration: February 26-28, 2008

Final Report Date: March 24, 2008

Contents

Introduction

Certification

General Inspection Procedures

Results of Visual Inspection

Bulk Sample Results

Summary of ACM Materials

Summary of Asbestos Containing Materials

Conclusion

Recommendations

Appendices

A. Asbestos Inspector Credentials

B. Fibertec IHS NVLAP Certification

C. Bulk Sample Log

D. Bulk Sample Analytical Report

E. Room by Room Asbestos Building Inspection Forms

F. Floor Plan Drawing with Sample Locations

G. Photograph Log

ASBESTOS BUILDING INSPECTION REPORT

for
Michigan State University
Old Horticulture Building
Project #24990-1

INTRODUCTION

Fibertec Industrial Hygiene Services, Inc. (Fibertec IHS) was retained by Michigan State University to perform an inspection for asbestos containing materials at Michigan State University, Old Horticulture Building, East Lansing, Michigan. The project was discussed with Mr. Zach Hansmann of the Michigan State University Office of Environmental Health and Safety prior to beginning the fieldwork. The inspection was designed to identify asbestos-containing materials within the building. The inspection was conducted pursuant to the inspection requirements of the Occupational Safety and Health Administration (OSHA), General Industry Standard for Asbestos, 29 CFR 1910.1001 and the Environmental Protection Agency (EPA) Asbestos Sampling Bulletin, dated September 30, 1994.

The asbestos building inspection took place on March 25-26, 2008. During the inspection, bulk samples of suspect asbestos-containing material (ACM) were collected. Collected asbestos bulk samples were submitted to the Fibertec IHS Polarized Light Microscopy (PLM) laboratory for analysis using EPA Method EPA/600/R-93/116.

CERTIFICATION

Mr. John Luna and Mr. Darrell DeMasters, State of Michigan accredited asbestos building inspectors, conducted the building inspection. Mr. Luna and Mr. DeMasters also maintain accreditation as Asbestos Contractor/Supervisors. A copy of their asbestos inspector credentials appear in Appendix A.

Trained polarized light microscopists analyzed all bulk asbestos samples in the Fibertec IHS Polarized Light Microscopy (PLM) laboratory. This laboratory maintains current National Voluntary Laboratory Accreditation Program (NVLAP) accreditation (Lab Code 101510-0). A copy of the Fibertec IHS NVLAP accreditation certificate appears in Appendix B.

GENERAL INSPECTION PROCEDURES

In an effort to identify asbestos-containing material (ACM) in all areas of the facility, an extensive inspection procedure was followed. A visual inspection of all rooms in the Old Horticulture Building was combined with the collection of an appropriate number and distribution of bulk samples. The visual inspection included all rooms of the building.

Determination of suspect asbestos-containing material was based on visual examination, bulk sample analysis, material age and professional experience. Specifically, materials similar in color and texture were classified into homogenous areas (*e.g.*, various plasters). An appropriate number and distribution of samples were collected from material in each homogenous area. All samples were analyzed by polarized light microscopy. When the results of analysis of all samples from a homogenous area indicate no asbestos present (less than or equal to one percent) the homogenous area is considered to be a non-asbestos containing material. When the results of analysis indicate asbestos present (in a quantity greater than one percent) in just one sample of those collected from a single homogenous area, the material in the entire homogenous area must be considered asbestos containing.

Destructive testing (*i.e.*, demolition) was not conducted as part of this asbestos building inspection. As such, quantities of ACM believed to exist in inaccessible areas (like pipe joint and hanger insulation in wall cavities or above the plaster ceilings) have not been accounted for in this inspection. Additionally, some asbestos-containing material hidden from view may be present and may not have been accounted for as part of this inspection.

RESULTS OF VISUAL INSPECTION

Based on the inspection, 23 distinct suspect asbestos-containing materials were identified in the inspection of the Old Horticulture Building, East Lansing, Michigan. Some suspect asbestos-containing materials were sampled a number of times in different locations, plaster, being an example. All suspect asbestos-containing materials observed at the time of the inspection are listed in the Room by Room Asbestos Building Inspection Forms. Information from lab analysis of collected samples is incorporated into the Room by Room Asbestos Building Inspection Forms to facilitate interpretation of the data.

BULK SAMPLE RESULTS

The information gathered from the inspection is included in Appendices C (Bulk Sample Log), D (Bulk Sample Analytical Report), E (Room by Room Asbestos Building Inspection Forms), F (Floor Plan Drawing with Sample Locations) and G (Photograph Log). The lab analysis reports give a description of each sample, location where each sample was collected, and the results of analysis.

SUMMARY OF ASBESTOS-CONTAINING MATERIALS

The following material was found to contain asbestos at the Old Horticulture Building:

12" x 12" green floor tile with white streaks and associated mastic (Although the floor tile was found not to contain asbestos, the black mastic was found to contain asbestos. As such, the tile will become contaminated by the mastic during removal and should be considered asbestos-containing material.)

The following materials were assumed to contain asbestos at the Old Horticulture Building:

Fire door and frame
Ceramic tile bedding compound
Roofing materials and products
Window and door frame caulk compound
Green chalkboards

The following materials were found not to contain asbestos at the Old Horticulture Building:

2" x 2" white drop-in ceiling tile with pin holes and fissures
2" x 2" white lay-in ceiling tile with pin holes and fissures
12" x 12" gray floor tile with white and gray marble pattern and associated mastic
Smooth wall and ceiling plaster over drywall
4" green cove molding and associated mastic
4" black cove molding and associated mastic
4" brown cove molding and associated mastic
6" brown cove molding and associated mastic
4" white cove molding and associated mastic
12" x 12" green floor tile with marble pattern and associated mastic
Pyrobar fire brick
Smooth plaster skim coat over brown coat
12" x 12" white ceiling tile with fissures and associated glue pods
Skim coat plaster over concrete steps
12" x 12" white ceiling tile with pinholes and associated glue pods
Gray sink undercoating

CONCLUSION

Non-friable (cannot be crumbled, pulverized or reduced to powder by hand pressure when dry) known or assumed asbestos-containing materials (*e.g.*, fire doors, floor tile mastic) were identified at the Old Horticulture Building.

RECOMMENDATIONS

Based on the information collected during this asbestos building inspection, the following recommendations are offered. These recommendations are based on plans to maintain the building in its current configuration and use and may have to be adjusted if change of ownership, emergency, or other factors alter the condition, use or planned use of the building.

Perform the following in this case:

1. Notify the owner, building maintenance staff, and contractors of the presence of ACM within the building. Ensure that contractors who work in the vicinity of or who may encounter asbestos-containing materials during the course of their work have successfully completed appropriate training. Ensure that contractors who work in the vicinity of or who may disturb asbestos-containing materials, do so pursuant to the requirements of the Asbestos in Construction Standard 29 CFR 1926.1101.
2. Provide two-hour asbestos hazard awareness training including specific information regarding the quantity, condition and location of ACM for those individuals in the building who may encounter asbestos during the course of their work. Ensure that contractors performing work in or on the building have equivalent training (at a minimum) and provide appropriate documentation.
3. Label ACM in routine maintenance areas, Mechanical Rooms and Custodial Closets, as required by 29 CFR 1910.1200(7)(vii).
4. Plan for the proper removal of any ACM that might be impacted by renovation or demolition prior to any renovation or demolition.

John Luna
Michigan Accredited Asbestos Inspector #A4665

Darrell DeMasters
Michigan Accredited Asbestos Inspector #A31159

Phillip A. Peterson
Vice President