

Michigan State University
Beaumont Tower - Asbestos Inspection Photo Log



Beaumont Tower (#12)

Michigan State University
Beaumont Tower - Asbestos Inspection Photo Log



HA #1 – Non asbestos containing plaster with light texture

Michigan State University
Beaumont Tower - Asbestos Inspection Photo Log



HA #2 – Non asbestos containing 4” black cove molding and associated mastic

Michigan State University
Beaumont Tower - Asbestos Inspection Photo Log



HA #3 – Asbestos containing black and brown building caulk

Michigan State University
Beaumont Tower - Asbestos Inspection Photo Log



HA #4 – Non asbestos containing black vinyl waterproof material

Michigan State University
Beaumont Tower - Asbestos Inspection Photo Log



HA #5 – Assumed asbestos containing 6” khaki cove molding and associated mastic

Michigan State University
Beaumont Tower - Asbestos Inspection Photo Log



HA #6 – Asbestos containing pipe insulation between floors

Michigan State University
Beaumont Tower - Asbestos Inspection Photo Log



HA #7 – Non asbestos containing brown exterior door caulk

HA #8 – Asbestos containing white door stop caulk