

Michigan State University Old Botany Building #17

Old Botany Photo Log



HA #1 – Non asbestos-containing plaster (wall and ceiling)



HA #2 – Non asbestos-containing drywall


HA #3 – Asbestos-containing drywall joint compound



HA #4 – Asbestos-containing steam/condensate supply and return pipe straight insulation



HA #5 – Asbestos-containing steam/condensate supply and return pipe joint and hanger insulation



HA #6 – Non asbestos-containing 2' x 2' white lay-in ceiling tile with pin holes and fissures



HA #8 – Non asbestos-containing 12" x 12" white ceiling tile with gouges and associated glue pods



HA #9 – Non asbestos-containing 4" black cove molding and associated non-asbestos containing mastic




HA #10 – Asbestos-containing 9" x 9" gray floor tile with black and white streaks and associated non asbestos-containing mastic



HA #11 – Asbestos-containing 9" x 9" light brown floor tile with white and rust streaks and associated mastic



HA #12 – Asbestos-containing 9" x 9" tan floor tile with white and rust streaks and associated non asbestos-containing mastic



HA #13 – Asbestos-containing 9" x 9" beige floor tile with pink, white and brown streaks and associated non asbestos-containing mastic



HA #14 – Non asbestos-containing 9" x 9" green floor tile with green streaks and associated asbestos-containing mastic




HA #15 – Asbestos-containing 9" x 9" red floor tile with cream streaks and associated non asbestos-containing mastic




HA #16 – Non asbestos-containing 9" x 9" white floor tile with tan marble pattern and associated asbestos containing mastic




HA #17 – Non asbestos-containing 9" x 9" white floor tile with black streaks and associated asbestos containing mastic



HA #18 – Non asbestos-containing 12" x 12" gray floor tile with gray and white marble pattern and associated mastic



HA #19 – Asbestos-containing 12" x 12" tan floor tile with white and rust streaks and associated non asbestos-containing mastic




HA #20 – Non asbestos-containing 12" x 12" beige floor tile with pink, white and brown streaks and associated mastic



HA #21 – Non asbestos-containing 12" x 12" white floor tile with tan marble pattern and associated mastic



HA #22 - Non asbestos-containing black stair tread and associated mastic



HA #23 – Asbestos-containing steam/condensate heat exchange tank insulation



HA #24 – Asbestos-containing ventilation duct expansion cloth



HA #25 – Assumed asbestos-containing chalkboards and associated glue pods




HA #26 – Assumed asbestos-containing fire door and frame



HA #27 – Assumed asbestos-containing window and door frame caulk compound



HA #30 – Non asbestos-containing attic insulation



HA #31 – Asbestos-containing domestic water supply pipe straight insulation



HA #32 – Asbestos-containing domestic water supply pipe joint and hanger insulation



HA #33 – Non asbestos-containing 6" black cove molding and associated mastic