

Auditorium Photo Log



HA #1 – Non asbestos-containing plaster

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #2 – Non asbestos-containing drywall

HA #3 – Asbestos-containing drywall joint compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #4 – Asbestos-containing 9" x 9" light green floor tile with cream and gray streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #5 – Asbestos-containing 9" x 9" light green floor tile  
with cream and black streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #6 – Asbestos-containing 9" x 9" black floor tile with cream and green streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

## Auditorium Photo Log



HA #7 – Asbestos-containing 12" x 12" dark green floor tile with cream, orange and green swirls and associated non asbestos-containing mastic

HA #8 – Asbestos-containing 12" x 12" black floor tile with cream and green streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #9 – Non asbestos-containing 6" black cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #10 – Non asbestos-containing 4" olive cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



Auditorium Photo Log



HA #13 – Asbestos-containing 1' x 2' black border floor tile  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #14 – Non asbestos-containing brown linoleum flooring  
with wood grain pattern and associated backing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #15 – Non asbestos-containing red linoleum flooring  
and associated backing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #17 – Asbestos-containing brown glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #18 – Asbestos-containing steam/condensate supply and return pipe straight insulation

HA #19 – Asbestos-containing steam/condensate supply and return pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #21 – Asbestos-containing domestic water supply and return pipe straight insulation

HA #22 – Asbestos-containing domestic water supply and return pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #25 – Non asbestos-containing white sink undercoating

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #27 – Non asbestos-containing cream mosaic pattern linoleum  
and associated backing

HA #28 – Non asbestos-containing 4" aqua cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



Auditorium Photo Log



HA #31 – Non asbestos-containing spray-on fireproofing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #32 – Non asbestos-containing 12" x 12" black floor tile with white specks and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #33 – Asbestos-containing 9" x 9" brown floor tile  
with cream and red streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #35 – Asbestos-containing 12" x 12" light brown floor tile  
with cream and red swirls and associated mastic

HA #36 – Asbestos-containing 12" x 12" dark brown floor tile  
with cream and red streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Auditorium Photo Log



HA #37 – Asbestos-containing 9" x 9" pink floor tile  
with cream and red streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #39 – Non asbestos-containing 12" x 12" white ceiling tile with uniform holes and associated asbestos-containing glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #40 – Asbestos-containing 9" x 9" tan floor tile with cream, pink and black streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Auditorium Photo Log



HA #47 – Asbestos-containing 12" x 12" tan floor tile with cream, pink and black streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



Auditorium Photo Log



HA #57 – Non asbestos-containing ventilation duct expansion cloth

For more information contact MSU Environmental Health and Safety – (517) 353-8956