

MSU, Computer Center Building



HA #1 – Non asbestos containing smooth plaster



HA #2 – Non asbestos 12" x 12" tan marble pattern floor tile and associated asbestos containing mastic



HA #3 – Non asbestos containing domestic water supply pipe straight insulation




HA #4 – Asbestos containing domestic water supply pipe joint and hanger insulation



HA #5 – Asbestos containing steam/condensate supply and return pipe straight insulation



HA #6 – Asbestos containing steam/condensate supply and return pipe joint and hanger insulation



HA #7 – Asbestos containing hot water holding tank insulation



HA #8 – Asbestos containing ventilation duct expansion cloth



HA #9 – Asbestos containing 6" black cove molding and associated non asbestos containing mastic



HA #10 – Asbestos containing 9" x 9" brown floor tile with cream and red streaks and associated non asbestos containing mastic



HA #11 – Asbestos containing 9" x 9" rust floor tile with cream and red streaks and associated non asbestos containing mastic



HA #13 – Non asbestos containing 4" black cove molding and associated mastic



HA #19 – Assumed asbestos containing chalkboards and associated glue pods



HA #20 – Assumed asbestos containing fire door and frame



HA #22 – Non asbestos containing 12" x 12" blue marble pattern floor tile and associated mastic



HA #23 – Non asbestos containing 6" gray cove molding and associated mastic



HA #28 – Non asbestos containing 12" x 12" apple green floor tile with marble pattern and associated mastic




HA #29 – Asbestos containing 9" x 9" tan floor tile with swirl pattern and associated non asbestos containing mastic




HA #31 – Asbestos containing 12" x 12" black floor tile with cream and red streaks and associated non asbestos-containing mastic

and


HA #32 – Asbestos containing 12" x 12" dark brown floor tile with brown and red streaks and associated non asbestos containing mastic



HA #44 – Asbestos containing 9" x 9" brown floor tile with multi-colored brown speckles and non asbestos containing associated mastic



HA #46 – Assumed asbestos containing window and door frame caulk compound



HA #46 – Assumed asbestos containing window and door frame caulk compound