




MSU Engineering Building



HA #1 – Non asbestos containing smooth plaster over drywall




HA #1 – Non asbestos containing smooth plaster over drywall




HA #3 – Non asbestos containing black sink undercoating




HA #4 – Non asbestos containing 2' x 2' white lay-in ceiling tile with pin holes and fissures




HA #5 – Non asbestos containing 2' x 4' white lay-in ceiling tile with pin holes




**HA #6 – Non asbestos containing 12” x 12” white floor tile with
black and gray marble pattern and associated mastic**




**HA #7 – Non asbestos containing 12” x 12” white floor
tile with green marble pattern and associated mastic**



**HA #8 – Non asbestos containing 12” x 12” white floor tile
with green, rust and tan specks and associated mastic**




**HA #9 – Non asbestos containing 12” x 12” tan floor tile
with marble pattern and associated mastic**




**HA #10 – Non asbestos containing 12” x 12” beige floor
tile with marble pattern and asbestos containing associated mastic**




HA #11 – Non asbestos containing 12” x 12” red floor tile
with marble pattern and asbestos containing associated mastic



HA #12 – Asbestos containing 12” x 12” dark brown floor tile with cream and green streaks and non asbestos containing associated mastic



**HA #13 – Asbestos containing 9” x 9” green floor tile
with white streaks and non asbestos containing associated mastic**




HA #14 – Asbestos containing 9” x 9” beige floor tile with pink, cream and brown swirl pattern and non asbestos containing associated mastic




HA #15 – Asbestos containing 9” x 9” light brown floor tile with cream and brown streaks and non asbestos containing associated mastic



HA #16 – Asbestos containing 9” x 9” gray floor tile with black and cream streaks and non asbestos containing associated mastic



HA #17 – Non asbestos containing 4” black cove molding
and associated mastic



HA #18 – Non asbestos containing 4” brown cove molding
and associated mastic




HA #19 – Non asbestos containing 4” gray cove molding
and associated mastic



HA #20 – Non asbestos containing 4” olive green
cove molding and associated mastic



**HA #21 – Non asbestos containing 4” beige cove molding
and associated mastic**



HA #22 – Non asbestos containing brown linoleum flooring
with tan streaks and associated mastic




HA #23 – Non asbestos containing window and door frame caulk compound (interior)



HA #24 – Non asbestos containing window and door frame
caulk compound (exterior)




HA #25 – Non asbestos containing building caulk compound




HA #26 – Non asbestos containing gray ventilation duct mastic



HA #27 – Assumed asbestos containing fire door and frame




HA #28 – Assumed asbestos containing chalkboards and associated glue pods



HA #29 – Assumed asbestos containing black laboratory
sinks, countertops and tables



**HA #31 – Non asbestos containing 12” x 12” cream floor tile
with marble pattern and asbestos containing associated mastic**



HA #32 – Non asbestos containing 12" x 12" rust floor tile with
marble pattern and asbestos containing associated mastic



HA #33 – Non asbestos containing 12" x 12" blue floor tile with
marble pattern and asbestos containing associated mastic



HA #34 – Non asbestos containing 12” x 12” gray floor tile with
marble pattern and associated mastic




HA #35 – Non asbestos containing 12” x 12” green floor tile
with marble pattern and associated mastic




HA #36 – Non asbestos containing 4" green cove molding
and associated mastic




HA #37 – Assumed asbestos containing transite fume hood




HA #38 – Non asbestos containing 6" black cove
molding and associated mastic



**HA #39 – Asbestos containing 9” x 9” light green floor tile
with green and gray streaks and non asbestos containing associated mastic**



HA #40 – Non asbestos containing gray sink undercoating



HA #41 – Non asbestos containing peach linoleum flooring
and associated mastic