

Michigan State University  
Asbestos Inspection Photo Log



MSU Water Reservoir (#96)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University  
Asbestos Inspection Photo Log



HA #1 – Assumed asbestos containing lab bench, sink, and drying rack

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University  
Asbestos Inspection Photo Log



HA #2 – Non asbestos containing 4” black cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University  
Asbestos Inspection Photo Log



HA #3 – Assumed asbestos containing fire door and frame

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University  
Asbestos Inspection Photo Log



HA #4 – Asbestos containing brown window glazing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University  
Asbestos Inspection Photo Log



HA #5 – Asbestos containing black roof tar

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University  
Asbestos Inspection Photo Log



HA #6 – Non-asbestos containing corrugated material

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University  
Asbestos Inspection Photo Log

Not Pictured

HA #7 – Asbestos containing dark brown window caulk

For more information contact MSU Environmental Health and Safety – (517) 353-8956



Michigan State University  
Asbestos Inspection Photo Log



HA #8 – Non-asbestos containing white decking patch

(Associated black roof tar is positive)

For more information contact MSU Environmental Health and Safety – (517) 353-8956