

HA #1 – Non asbestos-containing ceiling plaster



HA #4 – Non asbestos-containing 4" brown cove molding and associated mastic



 ${
m HA~\#5-Non~asbestos\text{-}containing~tan~mosaic~pattern~linoleum}$ and associated backing



HA #12 – Non asbestos-containing 2' x 2' white drop-in ceiling tile with pin holes and fissures



HA #13 – Non asbestos-containing canvas wrap on fiberglass pipe straight insulation



HA #14 – Asbestos-containing domestic water pipe joint and hanger insulation



HA #15 – Significantly damaged asbestos-containing transite paneling



HA #16 – Non asbestos-containing 12" x 12" tan floor tile with cream and brown specks and associated mastic



HA #17 – Asbestos-containing white sink undercoating



HA #18 – Non asbestos-containing 12" x 12" tan floor tile with marble pattern and associated mastic



HA #19 – Non asbestos-containing 2' x 4' white lay-in ceiling tile with pin holes and fissures



HA #20 – Non asbestos-containing 4" black cove molding and associated mastic