

Photo 1 – Asbestos-containing steam/condensate pipe joint insulation



Photo 2 – Asbestos-containing domestic water pipe joint insulation



Photo 3 – Asbestos-containing ventilation duct expansion cloth



Photo 4 – Asbestos-containing sewer drain pipe joint insulation



Photo 5 – Asbestos-containing 9" x 9" beige floor tile with swirls and associated mastic



Photo 6 – Non-asbestos containing plaster



Photo 7 – Asbestos-containing green lab table



Photo 8 – Non-asbestos containing black lab sink and table tops



Photo 9 – Non-asbestos containing 12" x 12" green marble pattern floor tile and associated mastic



Photo 10 – Non-asbestos containing 12" x 12" cream marble pattern floor tile and associated mastic



Photo 11 – Asbestos-containing electrical insulation cloth



Photo 12 – Non-asbestos containing 12" x 12" light cream floor tile with gray specks and associated mastic



Photo 13 – Asbestos-containing 9" x 9" light brown floor tile with cream and rust streaks and associated mastic



Photo 14 – Non asbestos-containing spray-in acoustical plaster



Photo 15 – Non asbestos-containing 2' x 2' brown linoleum and stair tread with cream swirls and associated mastic



Photo 16 – Non asbestos-containing tan textured sink undercoating



Photo 17 – Non asbestos-containing tan linoleum with cream streaks and associated mastic