

Michigan State University
Asbestos Inspection Photo Log



North Campus Substation (#516)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #1 – Non asbestos containing Gray Styrofoam insulation and associated brown gluepods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #2 – Assumed asbestos containing vibration collar

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #3 – Assumed asbestos containing white electrical line wrap

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #4 – Non asbestos containing Grey wall caulk

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #5 – Assumed asbestos containing fire door and frame

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #6 – Assumed asbestos containing 12”-36” metal jacketed steam line insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #7 – Non asbestos containing melted tar material

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #8 – Assumed asbestos containing tank insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #9 – Non-asbestos containing wall penetration fireproofing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #10 – Assumed asbestos containing 0”-12” metal jacketed steam line

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #11 – Non asbestos containing black pipe covering

For more information contact MSU Environmental Health and Safety – (517) 353-8956