

Michigan State University
Asbestos Inspection Photo Log



Pathological Incinerator (#524)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #1 – Non asbestos containing mud fittings on fiberglass

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



#2 Assumed Fire Door and Frame

For more information contact MSU Environmental Health and Safety – (517) 353-8956