Personal Protective Equipment Hazard Assessment Certification

M	IIC	1	110	34	N	S	T_{α}	AT	Έ
Ū	Ν	Ι	V	Ε	R	S	I	Т	Y

Job Title: Laboratory Worker	Date : 09/17/03
Department: All	Supervisor:
Location / Worksite: Research Buildings	Analysis: Dave Erickson
Employee Name(s):	Signature:

Tasks, Job Classification or Workstation	Potential Hazard	Type of PPE Required	PPE Required (Yes / No)
Working with low hazard chemicals when a low probability of splash exists	Skin and eye irritation	Safety glasses, Light chemical resistant gloves, Lab coat, closed shoe, pants	Y
Working with smaller amounts (<1 liter) of corrosive or injurious chemicals where a reasonable probability of splash exists	Skin and eye damage	Chemical splash goggles, Light chemical resistant gloves, Lab coat, closed shoe, pants	
Working with larger quantites of corrosive liquids (> 1 liter), or toxic corrosives	Large surface area skin and eye damage, Poisoning, or Great potential for eye and skin damage	Chemical splash goggles & face shield, Appropriate heavy resistant gloves Lab coat, closed shoes, pants and chemical resistant apron	Y
Working with small volumes of organic solvents (< 1 liter)	Skin and eye damage Slight poisoning potential through skin absorption	Safety glasses, goggles if splash hazard exists, Light chemical resistant gloves Lab coat, closed shoe, pants	Y
Working with large volumes of organic solvents (> 1 liter), highly toxic organic solvents or work which may create a splash hazard	Major skin and eye damage Potential poisoning through skin absorption	Safety goggles & face shield Appropriate heavy resistant gloves Above clothes and chemical resistant apron	Y