

Photo 1 – Non asbestos-containing spray-on acoustical ceiling plaster



Photo 2 – Non asbestos-containing ceiling glue pods



Photo 3 – Asbestos-containing 9" x 9" gray floor tile with white and rust streaks



Photo 4 - 12" x 12" white floor tile with gray specks



Photo 6 – Asbestos-containing 9" x 9" tan floor tile with cream, pink and brown streaks



Photo 6 – Asbestos-containing 12" x 12" tan floor tile with cream and brown streaks



Photo 7 – Assumed asbestos-containing window frame glazing compound



Photo 8 – Asbestos-containing 12" x 12" gray floor tile with marble pattern



Photo 9 – Asbestos-containing 12" x 12" tan floor tile with cream and brown streaks



Photo 10 – Non asbestos-containing tan linoleum with cream and black streaks




Photo 11 – Assumed asbestos-containing window and door frame caulk compound



Photo 12 – Giltner Hall