

Michigan State University
Asbestos Inspection Photo Log



Entomology Storage (#130)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #1 – Asbestos containing white to gray window glazing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Asbestos Inspection Photo Log



HA #2 – Assumed asbestos containing roofing materials and products

For more information contact MSU Environmental Health and Safety – (517) 353-8956