

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



Soil Science Lab (#430A)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #1 – Non asbestos containing light brown wallboard and paper layer

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #2 – Asbestos containing white glazing compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #3 – Asbestos containing brown wallboard gluepod

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #4 – Asbestos containing transite wall board

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #5 – Non asbestos containing sink

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #6 – Non-asbestos containing drywall on wood, unfinished

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #7 – Non asbestos containing seamless floor covering (canvas)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #8 – Asbestos containing plaster patch compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #9 – Asbestos containing white duct wrap

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #10 – Non-asbestos containing brown paper with tar layer

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #11 – Asbestos containing black tar on brown insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #12 – Non asbestos containing roofing materials (shingles)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Lab - Asbestos Inspection Photo Log



HA #13 – Asbestos containing brown transite siding panels

For more information contact MSU Environmental Health and Safety – (517) 353-8956