

Dairy Cattle Teaching and Research Main Barn Photo Log



HA #1 – Non asbestos containing 9” x 9” green floor tile with white and black streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Dairy Cattle Teaching and Research Main Barn Photo Log



HA #2 – Non asbestos containing 9” x 9” white floor tile with black streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Dairy Cattle Teaching and Research Main Barn Photo Log



HA # 4 – Non asbestos containing 2' x 4' lay-in white ceiling tile with raised 4" x 4" squares with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Dairy Cattle Teaching and Research Main Barn Photo Log



HA #3 – Asbestos containing transite wall and ceiling panels

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Dairy Cattle Teaching and Research Main Barn Photo Log



HA #5 – Assumed asbestos containing chalkboards
and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #6 – Asbestos containing light heat shield insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #9 – Asbestos containing domestic water supply
pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #8 – Asbestos containing steam/condensate supply
and return pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #7 – Non asbestos containing canvas wrap on fiberglass pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #11 – Asbestos containing drain line pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Dairy Cattle Teaching and Research Main Barn Photo Log



HA # 15 – Non asbestos containing multi-colored square pattern linoleum and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Dairy Cattle Teaching and Research Main Barn Photo Log



HA # 16 – Non asbestos containing 4” white cove
molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #14 – Non asbestos containing pink sink
undercoating insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA # 18 – Assumed asbestos containing
transite roof vent covers

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Dairy Cattle Teaching and Research Main Barn Photo Log



HA # 17 – Asbestos containing window and door
frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956